PAT-NO:

JP359189613A

DOCUMENT-IDENTIFIER: JP 59189613 A

TITLE:

IGNITION COIL FOR INTERNAL-COMBUSTION ENGINE

PUBN-DATE:

October 27, 1984

**INVENTOR-INFORMATION:** 

NAME

HASE, YUKIO

ASSIGNEE-INFORMATION:

NAME

COUNTRY

NIPPON DENSO CO LTD

N/A

APPL-NO:

JP58066235

APPL-DATE:

April 13, 1983

INT-CL (IPC): H01F031/00, H01F027/32

US-CL-CURRENT: 323/360, 505/870

#### ABSTRACT:

PURPOSE: To improve the heat discharge to the fitting part and reduce the temperature of the whole coil and improve the quality by making the winding density of the center portion of the primary coil lower than that of the both side portions of the coil.

CONSTITUTION: A core 1 is composed of laminated rectangular silicon-steel plates. Holes 2, with which the core 1 is fitted to a body, are provided to both ends of the core 1 and the core 1 is tightened and fitted to the fitting

BEST AVAILABLE COPY

part of the body frame or the like by bolts. The core 2 is not only a core but also has a function of discharging the heat generated by the primary coil to the body frame. When the **core** is not fitted to the body, the temperature is higher than that when the **core** is fitted by 40∼60°C. The primary **bobbin** 

4, which is made of resin and molded after the **core** 1 is inserted, is divided into three winding ditches by rims 5a, 5b. For instance, 85∼95% of the whole winding of the primary coil 3 wound in the bobbin 4 is wound in the two ditches at the both ends and 5∼15% of the whole winding is wound in the center ditch. An insulation means such as insulating paper can be used as a substitute for the primary bobbin 4.

COPYRIGHT: (C)1984,JPO&Japio

### (B) 日本国特許庁 (JP)

①特許出願公開

## <sup>®</sup> 公開特許公報(A)<sup>\*</sup>

昭59-189613

**Dint. Cl.**<sup>3</sup> H 01 F 31/00 27/32

識別記号

庁内整理番号 6969—5E 8323—5E ❸公開 昭和59年(1984)10月27日

発明の数 1 審査請求 未請求

(全 3 頁)

◎内燃機関用点火コイル

创特

磨 昭58-66235

❷出 頭 昭58(1983)4月13日

⑩発明 者 長谷幸雄

刈谷市昭和町1丁目1番地日本 電袋株式会社内

切出 願 人 日本電装株式会社

刈谷市昭和町1丁目1番地

個代 理 人 弁理士 岡部隆

男 和 🖠

1. 詹訶の名称

内盤瞬間用点火はイル

#### 2. 特許鮮求の施設

コアの間機を車体等の取付部に取付固定する内機機関用点火コイルにおいて、前記コアの外間に 促けな一次ポピン又は始級都等の絶縁学数と、数 独録手数に名かれた一次コイルとを請え、この一次コイルの中央部の機械器度を同婚部の機能密度 より少なくした内機機関用点火コイル。

#### 9. 発明の絆板な貼明

本発明は内燃姆関用点火コイルの破棄を及に開するもので、一次コイルの基準を改良することにより、コイル発熱温度を下げ、時命を向上させるものである。

従来用知のパッテリー点火コイルは、ロア、良いは、一次ボビンの上に、宣告 0.8 m 程度のコイルを、3~4 間の範囲で、約400 回程度審査していた。その為、運転により、コイル中心部の発展が資かった。

以下本先列を図に乗す実施仰について説明する。 馬1回において、1以長方形のな事解被を機履し でなるコフで、関端に単体へ取付けるための礼を があいており、図示しないボルトにて車体フレー ム等の取付部に付付置定される。なお、コアをは 積心であると共に、一次コイルの発熱を車件フレー 人に放為する機能もあり、単体フレームへ取付 けた場合に対し、取付けない場合は(0で~60 でも温度が高くなる。4はコフ1をインサート成 形してなる傾取製の一次ボビンで、ツバ5ょ、5 りにより3つの名称に分割されている。 3 は他犯 ポピン4に参かれた一次コイルで、関端の色語に 金融数の B 5 ~ 9 5 好が適付けてあり、中心の借 架に 5 ~ 1 5 好過付けてある。

第2回はコイルの勘線構造を変えた場合のコイ ル各部の温度を載わした特性園で、従来の様に一 つの恩罪に全出叙を密密する楊毓撰道では、実施 で示すごとく、中央部で205℃、関略的で19 () でであるのに対し、課1回に示す様な分割低に したものでは、独談で示すごとく中央師で18♪ で、可強郎で185℃と下がっており、ピーク仏 皮は208でから185でL20やも低下し、毎 5 図に来す、地線用電脑の熱寿命特性圏(促性ボ リエステルワイヤーの鑑定ー舞会時間特性図)か るも分るように、205七0接命700時間に対 と185℃の寿命30D0時間と約4倍に丹命を 律はすことができる。また、一次スイルミの温度 が低下することにより、一次コイル8の外間に巻 かれる因示しない、二次コイルの根底も下げるこ とができ、コイル全体の完全を伸ばし、品質向上

四、銀3四は物賦用電線の構革命特性関である。 1…コア、2…取付孔、8…一次コイル、6… 一次ポピン。

化键入剪理士 寓 郎 雖


ができる。

なお、上述した実施例においては、一次ポピン 4 モッパ 5 a、 5 b により名牌を 3 つに分割した が、増額の別れがなければ、ツバ 5 a、 5 b を表 止しても阿珠の幼弟が得られる。また、一次ポピ ンもの代わりに継続紙等の絶縁手段を用いること もできる。

以上述べたように本発明においては、一枚スイルの動態を開催に多く態色、中心部を少なくしたととにより、最高発热部が単体フレー系等の取付部に近くなり、取付部への放熱が座くなり、全体のコイル程度が低下するので電線再合が仲以及変が過程を表現の場合は、電解の開始ランクを19ンク下げてコストダウンを計ることもできる。その上、一次ボビン等の機構手致の材質も最質的に向上することができるという優れた効果がある。

#### 4. 関節の簡単な説明

第1 図は半発明コイルの一実施例を示す更新の 銀斯顧図、第2 図は第1 図図ボコイルの総度特性



# This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

BLACK BORDERS

IMAGE CUT OFF AT TOP, BOTTOM OR SIDES

FADED TEXT OR DRAWING

BLURRED OR ILLEGIBLE TEXT OR DRAWING

SKEWED/SLANTED IMAGES

COLOR OR BLACK AND WHITE PHOTOGRAPHS

GRAY SCALE DOCUMENTS

LINES OR MARKS ON ORIGINAL DOCUMENT

REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY

## IMAGES ARE BEST AVAILABLE COPY.

OTHER:

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.